



GLOBAL GROUND WATER CONSULTANTS

M/s. Gayatri Ramky JV

Dr. Aman

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 26/06/2023

Village : Shekhupura

Block : Kandela Zone-II

District : Shamli, U.P.

Depth in Metres	Expected Litholog	Expected Water Quality
0-3	Surface soil	
3-17	Sandy clay	
17-35 [⊗]	Fine to medium sand	Good
35-41	clay	
41-59 [⊗]	Medium sand	Good
59-66	clay	
66-90 [⊗]	medium sand	Good
90-105	clay	
105-114 [⊗]	Medium sand	Good
114-130	clay	
130-145 [⊗]	Medium to coarse sand	Good
145-155	clay	
155-170	Kanker clay	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▼ WATER LEVEL : 16 METRES

(SRIKANTH)

Consulting Geologists, Geophysists & Ground Water Specialists



Scanned with OKEN Scanner