GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

WALL ATTENVIOLENT MINERALDS

Ref No:-B- 576

Date: - 22-05-2023

NAME OF SITE

GRAM PANCHAYAT- Mohaliyia Veeran BLOCK- Khutar DISTT- Shahjahanpur

NAME OF AGENCY

Carrier of major his liter religion to real paragraph to the property of the carrier of the second and the second

Special Countries, and a business builtings and dution in the lever includes

M/s NCC Ltd. Shahjahanpur

. A Makes



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc_agra@yahoo.com

ISO: 9001: 2015
Ground Water Survey Consultancy
Agra

REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- MOHALIYIA VEERAN, BLOCK- KHUTAR, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

and tool with detempts (") education has availed assess for possible

Introduction:

A Deep bore hole was drilled 130 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 22.May.2023.

as a real popular surventible to proporcial interpretations.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral.

Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table

S.No.	S.No. Depth range(m)		Lithology	Expected Water Quality		
1.	0 - 5	5	Surface soil			
2.	5 - 7	2	Dry sand			
3.	7 - 15	8	Clay kankar			
4.	15 - 37	22	Fine to Medium sand	Good		
5.	37 - 44	7	Clay kankar			
6.	44 - 57	13	Medium sand	Good		
7.	57 - 62	5	Clay kankar			
8.	62 - 71*	9	Medium sand	Good		
9.	71 - 79	8	Clay kankar			
10.	79 - 87*	8	Medium sand	Good		
11.	87 - 98	11	Clay kankar	1 4		
12.	98 - 125*	27	Medium sand & kankar	Good		
13.	125 - 130	5	Clay kankar			



Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

	- AGRA INDIA	SURVEY CONSULTANCY	豆	Ž.		logger Modet	# # # # # # # # # # # # # # # # # # #		IGIS/S/D4/21-22			19.17 udarsh gupta (vahar)	shahajahangur UP (OGGNGus	Logging Mimohally/a weeran	A S	Rho a N16 (SW;
0 5 10 15 20 25 30 35 40 45 50 55 60 65 70 75 20 65 90 95 100 105 110 115 120 125 130	- 80 - 10 - 10 - 10 - 10 - 10 - 10 - 10		50- I I I I I I I I I I I I I I I I I I I		190- 190- 190- 190- 190- 190- 190- 190-			50-		150- NOT THE PARTY OF THE PARTY	200-	hm m 200- N 1 1 1 1 1 1 1 1 1	300-	350-	400-	

