GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-B- 688

Date: - 29-05-2023

NAME OF SITE

GRAM PANCHAYAT- Purena BLOCK- Kanth

Character and Marketine and Artist 1991

the commendated the translated for a normal to say south his manifest the factor

the southeasterns to released himsology arms of these such accordance freight the same

the transfer of the Control of the C DISTT- Shahjahanpur

NAME OF AGENCY

the trigger and outlings are proceedings to be wing table

M/s NCC Ltd. Shahjahanpur

Parkethani.



GROUND WATER SURVEY CONSULTANC

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email; gwsc_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy

REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- PURENA, BLOCK- KANTH, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

allow with an and the application de avoided rooms for an officie

Introduction:

A Deep bore hole was drilled 120 mtrs. depth. and Logged depth 120 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 29.May.2023.

of reiner to payer and interpretablished

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 10	5 - 5	Dry sand	
3.	10 - 16	6,000,25	Clay kankar	
4.	16 - 22	6	Fine sand	Good
5.	22 - 40	18	Clay kankar	
6.	40 - 73*	33	Medium sand	Good
7.	73 - 78	5	Clay kankar	
8.	78 - 82	4	Fine sand	Good
9.	82 - 102	20	Clay kankar	- 7.4
10.	102 - 115*	1.3	Fine to Medium sand	Good
11.	115 - 120	5	Clay kankar	

Ground Water Survey Consultancy

Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.

merter of Antoportalitates

5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy



