



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029

Mobile : 9818 888 824, 9818 007 038

E-mail : srikanthchukka.c23@gmail.com, ravikanth44@yahoo.com

Mr. Aman

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :

Date : 12/04/2023

Village : Lank

Block : Shamli

District : Muzaffarnagar, U.P.

Depth in Metres	Expected Litholog	Expected Water Quality
0-3	Surface soil	
3-16	Sandy clay	
16-22 [⊗]	Fine to medium sand	
22-25	clay	
25-28 [⊗]	Medium sand	Good
28-47	clay Kanker	
47-50 [⊗]	Medium sand	Good
50-53	clay	
53-89 [⊗]	medium sand	Good
89-92	Sandy clay Kanker	
92-108 [⊗]	Medium sand	Good
108-123	clay	
123-141 [⊗]	Medium sand	Good
141-160	Sandy clay	
160-170	clay	

For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE

▽ WATER LEVEL :1.7... METRES

Consulting Geologists, Geophysists & Ground Water Specialists



Lac
 53 — 89 — 11.5m
 92 — 108 — 11.5m
 123 — 141 — 11.5m

3w → 60m²

2w → 40 m²

2w → 50 m²

