GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL **ELECTOLOGGING REPORT**

Ref No:-A07

Date:- 22-01-2023

NAME OF SITE

Gram Panchayat- Padra Sikandarpur BLOCK- Bhawalkhera

Balling a brown to the least of the confidence by the country of the community of

ing an in a substituted billion consumer of the recognition of the state of the same consumer. to the standard telegraphists and other or those temperatures being and selection which is it cannot a manage

DISTT- Shahjahanpur

NAME OF AGENCY

est the parein than this calling an are product in the light series for the

M/s NCC Ltd. Shahjahanpur



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc agra@yahoo.com

ISO; 9001; 2015

Ground Water Survey Consultancy

REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- PADRA SIKANDARPUR, BLOCK- BHAWALKHERA, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

Carried 11 appear to be appared to the

Introduction:

A Deep bore hole was drilled 142 mtrs. depth. and Logged depth 140 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

the most a terror with the First control office could


On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 22.Jan.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral.

Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

and the strong property of the second could be designed the strength of the surrest of the court of the second

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 15	10	Clay kankar	
3.	15 - 26	11	Fine to Medium sand	Medium
4.	26 - 31	5	Clay kankar	
5.	31 - 36	5	Fine sand	Medium
6.	36 - 42	6	Clay kankar	
7.	42 - 52*	10	Fine to Medium sand	Medium
8.	52 - 56	4	Clay kankar	
9.	56 - 62	6	Kankar	
10.	62 - 70	8	Clay kankar	
11,	70 - 75*	5	Fine to Medium sand	Medium
12.	75 - 80	5	Clay kankar	
13.	80 - 96*	16	Medium sand	Medium
14.	96 - 99	3	Clay kankar	
15.	99 - 110*	11	Medium sand	Medium
16.	110 - 120	10	Kankar	
17.	120 - 132*	12	Medium sand	· Medium
18.	132 - 140	8	Clay kankar	



Conclusions and Recommendations :-

- The Lithology broadly tallies with that of drill cutting strata chart.
- 2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- The Quality of water is expected Medium.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

