



Aqua Xplore

(Groundwater Assessment & Allied Services)

243/5, New Colony Jiyamau, Hazratganj, Lucknow – 226001
Mob. 9918202546 / 9889323322, E mail- aquaxploreko@gmail.com

Advisor – Dr. R. A. Yadav, ex-Manager (Groundwater), U. P. Jal Nigam

Ref. 522 - M / AX - 2023

Date 22.05.2023

Geophysical Borehole Logging Report

Name of the site : Muradpur urf Belrai, Block - Bankati

District : Basti

Date : 22.05.2023

Depth logged : ~~134.0 mbgl~~

Depth drilled : 136.0 mbgl- as reported

Logger used : ~~Robertson make~~

Presence : Rep. of M/S Megha Engineering & Infrastructure Ltd., Hyderabad

Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water.

Sl.No.	Depth range(mbgl)	Thickness(m)	Remarks
1	30.0—38.0	8.0	Good all
2	43.0—50.0	7.0	
3	54.0—61.0	7.0	
4	68.0—92.0	24.0	
5	110.0—120.0	10.0	

Note. ~~All zones are intermixed with kankar. Sl. Nos. 1 & 2 are highly kankar intermixed.~~

Verified as per
logs provided.

for Aqua Xplore

To

M/S Megha Engineering & Infrastructure Limited, Hyderabad

G Sh
23/05/23

