

## Aqua Xplore

(Groundwater Assessment & Allied Services) 243/5, New Colony Jiyamau, Hazratganj, Lucknow - 226001 Mob. 9918202546 / 9889323322, E mail- aquaxplorelko@gmail.com

Advisor - Dr. R. A. Yadav, ex-Manager (Groundwater), U. P. Jal Nigam

Ref. 904 - B / AX - 2022

Date 04,09,2022

## Geophysical Borehole Logging Report

Name of the site : Dayalpur, Block - Bahadurpur

District

: Basti

Date

: 04.09.2022

Depth logged

: 130.0 mbgl

Depth drilled

: 135.0 mbgl- as reported

Logger used

: Robertson make

Presence

: Rep. of M/S Megha Engineering & Infrastructure Ltd., Hyderabad

Based on the interpretation of geophysical logs, following information may

be deciphered, particularly with respect to salinity of the formation water.

| SI,No.     | Depth range(mbgl)  |   | Thickness(m)                              | Remarks  |
|------------|--|---|---|----------|
| 12/4/4/6/6 | 12.0—28.0<br>40.0—50.0<br>58.0—63.0<br>73.0—83.0<br>88.0—95.0<br>114.0—118.0 | , | 16.0<br>10.0<br>5.0<br>10.0<br>7.0<br>4.0 | Good all |

intermixed with fine bands of kankar.

Verified as her ded.

for Aqua Xplore

M/S Megha Engineering & Infrastructure Limited, Hyderabad

