

Agua Xplore

(Groundwater Assessment & Allied Services)

243/5, New Colony Jiyamau, Hazratganj, Lucknow - 226001 Mob. 9918202546 / 9889323322, E mail- aquaxplorelko@gmail.com

Advisor - Dr. R. A. Yadav, ex-Manager (Groundwater), U. P. Jal Nigam

Ref. 930 - D / AX - 2022

Date 30.09.2022

Geophysical Borehole Logging Report

Name of the site : Dhobahat, Block - Bahadurpur

District

: Basti

Date

:30.09.2022

Depth logged

: 118.0 mbgl

Depth driiled

: 125.0 mbgl- as reported

Logger used

: Robertson-make

Presence

: Rep. of M/S Megha Engineering & Infrastructure Ltd., Hyderabad

Based on the interpretation of geophysical logs, following information may

be deciphered, particularly with respect to salinity of the formation water.

SI.No.	Depth range(mbgl)	Thickness(m)	Remarks
X	28.036.0	8.0	
2	52.0-56.0	6.0	Good all
3	76.0—84.0	8.0	
A	94.0104.0	10.0	

Note, All zones are intermixed with fine bands of kankar.

Verified as per logs provided.

for Aqua Xplore

for Aqual M/S Megha Engineering & Infrastructure Limited, Hyderabad 6% $36/9/2^2$.