# GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:- 791

Date: - 09-09-2022

## NAME OF SITE

कि महार्थ कर अंग्रेटिंग को स्वाक कि होता हुन है कर हो प्रतान के का

Gram Panchayat- Fazilpur

BLOCK- Madnapur

DISTT- Shahjahanpur

#### NAME OF AGENCY

M/s NCC Ltd. Shahjahanpur



### GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy

# REPORT ON GEOPHYSICAL WELL LOGGING AT

# GRAM PANCHAYAT- FAZILPUR, BLOCK- MADNAPUR DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 129 mtrs. depth. and Logged depth 121 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 09.Sep.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major equifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Defth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 10	5	Fine sand	
3	10 - 18	8	Clay kankar	
4.	18 - 26	8	Fine to Medium sand	Good
5.	26 - 31	5	Clay kankar	1
6.	31 - 48	17	Medium sand & Kankar	Good
7.	48 - 52	4	Clay kankar	
8.	52 - 90*	38	Medium sand & Kankar	Good
9.	90 - 95	5	Clay kankar	* 2 * 2 * 2
10.	95 - 105*	10	Fine to Medium sand	Good
11.	105 - 115	10	Clay kankar	
12.	115 - 121	6	Sandy clay	

Ground Water Survey Consultancy

#### Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting starta chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. Expected discharge is 900 to 1000 L.P.M.
- It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 6. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy



