## GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## **GEO-PHYSICAL WELL ELECTOLOGGING REPORT**

Ref No:- 458

Date: - 27-06-2022

#### NAME OF SITE

Gram Panchayat- Hatampur

BLOCK- Kalan DISTT- Shahjahanpur

### NAME OF AGENCY

M/s NCC Ltd. Shahjahanpur



## GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra-282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy

# REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- HATAMPUR, BLOCK- KALAN, DISTT- SHAHJAHANPUR
UNDER
JAL JIVAN MISSION

## Introduction:

A Deep bore hole was drilled 132 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 27.June.2022.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major equifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Defth range(m)	Thickness(m)	Lithology	Expected
1.	0 - 5	5		Water Quality
2.	5 - 16	and the second	Surface soil	
3.		11	Fine to Medium sand	
4.	16 - 27	11	Clay kankar	11.
5.	27 - 34	7	Medium sand	Good
	34 - 45	11	Clay kankar	3000
6.	45 - 56*	11	Medium sand	Good
7.	56 - 65	9	Clay kankar	Good
8.	65 - 76*	11	Medium sand	Cood
9.	76 - 82	6	Clay kankar	Good
10.	82 - 90	8	Kankar	
11.	90 - 103	13	Clay kankar	
12.	103 - 117*	14		
13.	117 - 130	***	Medium sand	Good
	1.7 1.50	13	Clay kankar	



#### Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting starta chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. Expected discharge is 800 to 900 L.P.M.
- 5. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 6. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

LAST COMMENTS CON CONT. COMMENTS COMMENTS COMMENTS TO FROM TO Rho a NI 6 (SN, LAT हे दे हैं 0pm m 8 2 8 35 6 ņ ÿ -10-8 **P** 5 **V-**5 5 **B-**3 쓩-딿**à**-გ-<u>ين</u> -8-65 70 Depth (m) 31-\_ **%**-2-**5**.**ž**-ន: ਛਾ 3 죵-125 쯍-

# Ground Water Survey Agranged \* Aguranten Agranged \* Aguranten Ag