



# Aqua Xplore

(Groundwater Assessment & Allied Services)

243/5, New Colony Jiyamau, Hazratganj, Lucknow - 226001

Mob. 9918202546 / 9889323322, E mail- aquaxploreelko@gmail.com

Advisor - Dr. R. A. Yadav, ex-Manager (Groundwater), U. P. Jal Nigam

Ref. 325 - B / AX - 2023

Date 25.03.2023

## Geophysical Borehole Logging Report

Name of the site : Belhsa, Block - Saltauva Gopalpur

District : Basti

Date : 25.03.2023

Depth logged : ~~133.0 mbgl~~

Depth drilled : 134.0 mbgl - as reported

Logger used : ~~Robertson Xplore~~

Presence : Rep. of M/S Megha Engineering & Infrastructure Ltd., Hyderabad

Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water.

Sl.No.	Depth range(mbgl)	Thickness(m)	Remarks
<del>1</del>	24.0—31.0	7.0	Good all
<del>2</del>	40.0—47.0	7.0	
<del>3</del>	50.0—60.0	10.0	
<del>4</del>	64.0—84.0	20.0	
<del>5</del>	88.0—98.0	10.0	
<del>6</del>	102.0—106.0	6.0	
<del>7</del>	127.0—131.0	4.0	

Note. All zones are intermixed with fine bands of kankar.

Verified as per  
logs provided

for Aqua Xplore

To

M/S Megha Engineering & Infrastructure Limited  
Hyderabad

G. Ch  
25/3/23