

# GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

## GEO-PHYSICAL WELL ELECTROLOGGING REPORT

Ref No:-A-1554

Date:- 03-09-2023

### NAME OF SITE

GRAM PANCHAYAT- Ahamd Nagar Jagir BLOCK- Chamaraua DISTT- Rampur

### NAME OF AGENCY

M/s PNC-SPML-JV

Rampur

22, CAMAC STREAT, BLOCK-A, 3<sup>rd</sup> FLOOR, KOLKATA-700016



## GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.

112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006

(M) : 9412260823, 9794625420, 9761163000, Email : gwsc\_agra@yahoo.com

ISO 9001 : 2015

Ground Water Survey Consultancy



# REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- AHAMD NAGAR JAGIR, BLOCK- CHAMARAUA, DISTT- RAMPUR  
UNDER  
JAL JIVAN MISSION

## Introduction :


A Deep bore hole was drilled 140 mtrs. depth. and Logged depth 140 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Rampur.

On the request of M/S PNC-SPML-JV, Rampur.. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 03.Sep.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 15	10	Clay kankar	
3.	15 - 20	5	Medium sand	
4.	20 - 30	10	Clay kankar	
5.	30 - 39	9	Medium sand	Medium
6.	39 - 44	5	Clay kankar	
7.	44 - 50*	6	Medium sand	Medium
8.	50 - 56	6	Clay kankar	
9.	56 - 61*	5	Medium sand	Medium
10.	61 - 65	4	Clay kankar	
11.	65 - 74*	9	Medium sand & kankar	Medium
12.	74 - 85	11	Clay kankar	
13.	85 - 92*	7	Medium sand	Medium
14.	92 - 96	4	Clay kankar	
15.	96 - 111*	15	Fine to Medium sand	Medium
16.	111 - 128	17	Clay kankar	
17.	128 - 137*	9	Medium sand	Medium
18.	137 - 140	3	Clay kankar	

Ground Water Survey Consultancy



**Conclusions and Recommendations :-**

1. The Lithology broadly tallies with that of drill cutting strata chart.
2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
3. The Quality of water is expected Medium.
4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist



Ground Water Survey Consultancy

