

Contract: m/s. Woodhill Indra Street



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
 Mobile : 9818 888 824, 9818 007 038
 E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Date : 21.02.2023


Tubewell No. :

Village : REDI MALAKPUR

Block : SAHARANPUR, U.P

District :

Depth in Metres	Expected Litholog	Expected Water Quality
0-3m	Surface Soil	
3-10	Sandy clay	
10-15 [⊗]	medium Sand	good
15-20	Sandy clay	
20-38 [⊗]	Coarse sand	good
38-41 [⊗]	medium sand	good
41-77 [⊗]	Coarse sand	good
77-92 [⊗]	medium to fine sand	good
92-112 [⊗]	Sand Boulders	good
112-118	Sandy clay	
118-132 [⊗]	medium sand	good
132-138	clay	
138-144 [⊗]	medium sand	good
144-165	clay kankar.	



For Global Groundwater Consultants

- ⊗ EXPECTED WATER ZONE
- ▽ WATER LEVEL :17..... METRES

M. Rao Kantu
 M. RAO KANTU
 21/2/2023