



Centre : m/s. L. C. Infra



GLOBAL GROUND WATER CONSULTANTS

84-III Floor, Humayunpur, Safdarjung Enclave, New Delhi - 110 029
 Mobile : 9818 888 824, 9818 007 038
 E-mail : srikanthchukka.c23@gamil.com, ravikanth44@yahoo.com

ms. Hari prasad

GEOPHYSICAL ELECTRICAL LOGGING REPORT AT

Tubewell No. :


Date : 11.10.2022

Village : CHOULHADA

Block : Bagh pat

District : Bagh pat, U.P

Depth in Metres	Expected Litholog	Expected Water Quality
0 - 3m	Sube soil	
3 - 8	clay	
8 - 20	Fine sand	
20 - 37	medium sand	good
37 - 40	clay	
40 - 56	medium sand	good
56 - 61	clay	
61 - 71	medium sand	good
71 - 80	clay	
80 - 91	Fine sand	good
91 - 109	clay	
109 - 115	medium sand	good
115 - 124	clay	
124 - 127	Fine sand	good
127 - 134	clay	
134 - 137	Very fine sand	good
137 - 143	clay	



For Global Groundwater Consultants

⊗ EXPECTED WATER ZONE
 ▼ WATER LEVEL :20..... METRES

Pratik
M. Ravi Prasad
1/10/2022

Consulting Geologists, Geophysists & Ground Water Specialists

Scanned by CamScanner

Fig 6 Water logging Report