

GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-B- 952

Date:- 15-06-2023

NAME OF SITE

GRAM PANCHAYAT- Kar Khera

BLOCK- Swar

DISTT- Rampur

NAME OF AGENCY

M/s PNC-SPML-JV

Rampur

22, CAMAC STREET, BLOCK-A, 3rd FLOOR, KOLKATA-700016



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006

(M) : 9412260823, 9794625420, 9761163000, Email : gwsc_agra@yahoo.com

ISO ; 9001 : 2015

Ground Water Survey Consultancy
Agra



REPORT ON GEOPHYSICAL WELL LOGGING AT

GRAM PANCHAYAT- KAR KHERA, BLOCK- SWAR, DISTT- RAMPUR
UNDER
JAL JIVAN MISSION

Introduction :

A Deep bore hole was drilled 130 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Rampur.

On the request of M/S PNC-SPML-JV, Rampur.. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 15.June.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 10	5	Clay kankar	
3.	10 - 14	4	Fine sand	
4.	14 - 22	8	Clay kankar	
5.	22 - 41	19	Medium sand	Good
6.	41 - 46	5	Clay kankar	
7.	46 - 57*	11	Medium sand & kankar	Good
8.	57 - 66	9	Clay kankar	
9.	66 - 73*	7	Fine to Medium sand	Good
10.	73 - 80	7	Clay kankar	
11.	80 - 100*	20	Medium sand	Good
12.	100 - 105	5	Clay kankar	
13.	105 - 115*	10	Medium sand	Good
14.	115 - 121	6	Clay kankar	
15.	121 - 126*	5	Fine to Medium sand	Good
16.	126 - 130	4	Clay kankar	

Ground Water Survey Consultancy



Conclusions and Recommendations :-

1. The Lithology broadly tallies with that of drill cutting strata chart.
2. The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
3. The Quality of water is expected Good.
4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist



Ground Water Survey Consultancy

Rho a
 N16 (SN)
 N84(LIN)
 LAT

Logging Details
 10/11/2013 10:00:00
 10/11/2013 10:00:00
 10/11/2013 10:00:00
 10/11/2013 10:00:00
 10/11/2013 10:00:00
 10/11/2013 10:00:00

Logger S No
 10/11/2013-24

SP (m V)
 Logger Model
 DMP1-2
 Logger Owned by
 Ground Water
 Survey Consultancy
 Agra UP India

