GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-N-956

Date: - 25-01-2023

NAME OF SITE

GRAM PANCHAYAT- Dhanaura

BLOCK- Shahabad DISTT- Rampur

NAME OF AGENCY

M/s PNC-SPML-JV Moradabad 22, CAMAC STREAT, BLOCK-A, 3rd FLOOR, KOLKATA-700016



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc agra@yahoo.com

> ISO; 9001: 2015 Ground Water Survey Consultancy

REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- DHANAURA, BLOCK- SHAHABAD, DISTT- RAMPUR UNDER JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 122 mtrs. depth. and Logged depth 122 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Moradabad.

On the request of M/S PNC-SPML-JV, Moradabad. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 25.Jan.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 10	5	Dry sand	
3.	10 - 14	4	Clay kankar	
4.	14 - 20	6	Fine sand	Medium
5.	20 - 23	3	Clay kankar	
6.	23 - 30	7	Fine to Medium sand	Medium
7.	30 - 33	3	Clay kankar	
8.	33 - 46	13	Medium sand	Medium
9.	46 - 50	4	Clay kankar	1110010111
10.	50 - 56*	6	Medium sand	Medium
11.	56 - 60	4	Clay kankar	THE GIGHT
12.	60 - 70*	10	Medium sand	Medium
13.	70 - 80	10	Clay kankar	Triedium
14.	80 - 97*	17	Fine to Medium sand	Medium
15.	97 - 100	3	Clay kankar	Triculani
16.	100 - 112*	12	Fine to Medium sand	Medium
17.	112 - 122	10	Clay kankar	iviculuiii



Conclusions and Recommendations :-

- The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- The Quality of water is expected Medium.
- It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

Ground water Survey Consultancy - Agra India DMPL-2 165/5/03/21-22 SP (m 1/) m V . နှင့် Ohm m Ç ğ 33-Ÿ. 8 ş 7 · -8-12-53-5-5-K3-60 65 Depth (m) 8-3-8-B-8-2-ᅙ-ᇙ-5-5-8-점-년

