

G.S.N  
02/04/23

To M/S Megha Engineering & Infrastructure Limited, Hyderabad  
for Aqua Xplore

Verified after logs provided  
Note S.NOS have few sediments  
@

Note: All zones are intermixed with kankar. Sl. Nos. 3 & 8 are highly kankar intermixed.

SI.No	Depth range(mbgl)	Thickness(m)	Remarks
1	20.0-24.0	4.0	Good all
2	38.0-45.0	7.0	
3	50.0-54.0	4.0	
4	60.0-66.0	6.0	
5	78.0-85.0	7.0	
6	89.0-93.0	4.0	
7	98.0-102.0	4.0	
8	112.0-118.0	6.0	
9	126.0-133.0	7.0	

Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water:  
Presence : Rep. of M/S Megha Engineering & Infrastructure Ltd, Hyderabad

Logger used : Robertson make  
Depth drilled : 140.0 mbgl  
Depth logged : 136.0 mbgl  
Date : 02.04.2023  
District : Basti

Name of the site : Dihpur urf Shukapur, Block - Kudraha

Geophysical Borehole Logging Report

Ref: 402 - D / AX - 2023 Date 02.04.2023

Advisor - Dr. R. A. Yadav, ex-Manager (Groundwater), U.P. Jal Nigam

(Groundwater Assessment & Allied Services)  
243/5, New Colony Jiyamau, Hazratganj, Lucknow - 226001  
Mob. 9918202546 / 9889323322, E mail- aquaxploreko@gmail.com

**Aqua Xplore**

