## GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

### GEO-PHYSICAL WELL **ELECTOLOGGING REPORT**

Ref No:-B- 907

Date: - 12-06-2023

#### NAME OF SITE

GRAM PANCHAYAT- Kakar Katha BLOCK- Mirzapur

DISTT- Shahjahanpur

### NAME OF AGENCY

M/s NCC Ltd. Shahjahanpur



### GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations. 112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006 (M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

> ISQ = 9001 : 2015 Ground Water Survey Consultancy

# REPORT ON GEOPHYSICAL WELL LOGGING

# GRAM PANCHAYAT- KAKAR KATHA, BLOCK- MIRZAPUR, DISTT- SHAHJAHANPUR UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 130 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S NCC Ltd., Shahjahanpur.

On the request of M/S NCC Ltd., Shahjahanpur. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 12.June.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality		
1.	0 - 5	- 5	Surface soil			
2.	5 - 8	3	Dry sand			
3.	8 - 15	7	Fine sand			
4.	15 - 25	10	Clay kankar			
5.	25 - 30	5	Fine sand	Medium		
6.	30 - 35	5	Clay kankar			
7.	35 - 45	10	Sand & kankar	Medium		
8.	45 - 48	3	. Clay kankar			
9.	48 - 62*	14	Medium sand	Medium		
10.	62 - 66	4	Clay kankar			
11.	66 - 71	5	Fine sand	Medium		
12.	71 - 85	14	Clay kankar			
13.	85 - 88	3	Fine sand	Medium		
14.	88 - 94	6	Clay kankar	1		
15.	94 - 103*	9	Fine to Medium sand	Medium		
16.	103 - 110	7.	'Clay kankar			
	110 - 120*	10	Fine to Medium sand	Medium		
17.	120 - 130	10	Clay kankar			

Ground Water Survey Consultancy

#### **Conclusions and Recommendations:**

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Medium.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.



**Ground Water Survey Consultancy** 

		Survey Consultancy 0-	m	v ; ;	-	666	50	IGI\$7\$/01/10-11	20	<b>8</b>	Ohm i	n <b>5</b>	TANK COURT	V LAT	100000000000000000000000000000000000000
0.	_			j	j			15			-	<del>,</del>	\$	70-	\$ :
5- 10-	=	1			>					6				3	
100		-	)			÷.		1.8	1	D		$\vdash$	-		/
25-		3			1.0	7 1	-	5	5		il NAV				
g-			ζ				-	>	>				+{	1791	
23-		711		1		= 1		1	-					1	
39-		1 4		5					<			5.		1	
35		1 = :			>			1				13. 13. 13. 13. 13. 13. 13. 13. 13. 13.		1	7
8-			1		र्			5	5	270	8	200	44.		
5-		19.1			1	3		3	3					$\langle -$	6-
8-				1	1	}				5	1 1 1			}	
85		12 mg	74 X		7			1	>	/		- 19	3		1 3
8-	The second second			,	1	. · ·		3		1164 1174 1174 1174			3		r 265
65	- Landerson			7	5		-{	1 1 1	7				1		-
ğ-					3	150	5				3.1	1 38	1		8
8-				\$			1		3				{	e e e	
8-		15	1	14			-{						{		
8-		- Y		2					7			*37 e	15	- I	
8-				7		Treff		-	5	7 2	N Villa Villa		1 }		
8-			1	1	1			3	1				1		4.7
8-	and the second s	*/ A	1 43	*	}			4	5	A.C	1 - 13	1 - III	1		
효-		7.		3				7	1			-	1	02.5	10.0- 1-
5		9 10 V		4	7			-	1	H. Luit		=======================================	1		
15		VAL.	$\dashv$		}	\$ 18 		1	- 11 - 12 - 12	iat.			100	_	
평-			.,	- K	1			1	1		2.10		1	-	<sup>7</sup> 1
й-	_			7	7	1.5			7	37			1	_	_

