GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-B-1170

Date:-29-06-2023

NAME OF SITE

GRAM PANCHAYAT- Masoodpura

BLOCK-Usawan

DISTT- Badaun

NAME OF AGENCY

M/s PNC-SPML-JV Badaun



GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc_agra@yahoo.com

ISO; 9001: 2015



REPORT ON GEOPHYSICAL WELL LOGGING

GRAM PANCHAYAT- MASOODPURA, BLOCK- USAWAN, DISTT- BADAUN
UNDER
JAL JIVAN MISSION

Introduction:

A Deep bore hole was drilled 140 mtrs. depth. and Logged depth 140 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JV, Badaun. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 29.June.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth range(m)	Thickness(m)	Lithology	Expected Water Quality
1.	0 - 5	5	Surface soil	
2.	5 - 17	12	Dry sand	
3.	17 - 59	42	Clay kankar	
4.	59 - 81*	22	Medium sand & kankar	Good
5.	81 - 105	24	Clay kankar	
6.	105 - 111*	6	Fine to Medium sand	Good
7.	111 - 116	5	Clay kankar	
8.	116 - 126*	10	Medium sand & kankar	Good
9.	126 - 140	14	Clay kankar	

Ground Water Survey Consultancy Agra

Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting strata chart.
- The zones marked with asterisk (*) appear to be aquifer zones for possible development of tubewell.
- 3. The Quality of water is expected Good.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Geophysicist

Ground Water Survey Consultancy

Sport NIP (Sec Ground Water Survey Consultancy Agra UP India שמטע שלונים TOTAL CHEER AL DIAPL-2 मन्द्रायात्रका SERVI Am 软软软软 Ohm m * * * * * * * * * * * * * * * F 海 岩 岩 嶷 F 5 0u-5-3-8.-2-8-35-8-3 8 55 Ground Wales Survey . 8 65 70 75 8-23-8-95 100 105 110 115 120 1000 ांठ । छ । छ। E