### GROUND WATER SURVEY CONSULTANCY

GEOLOGISTS, GEOPHYSICISTS & TUBEWELL ENGINEERS

# GEO-PHYSICAL WELL ELECTOLOGGING REPORT

Ref No:-A-1432

Date:- 18-08-2023

NAME OF SITE

GRAM PANCHAYAT- Kadeka

BLOCK- Datagani

DISTT- Badaun

NAME OF AGENCY

M/s PNC-SPML-JV Badaun



### GROUND WATER SURVEY CONSULTANCY

Electric Well Logging, Geophysical Resistivity Survey, Ground Water Investigations.
112 A-Shree Nagar Colony, Firozabad Road, Agra- 282006
(M): 9412260823, 9794625420, 9761163000, Email: gwsc\_agra@yahoo.com

ISO; 9001: 2015

Ground Water Survey Consultancy

## REPORT ON GEOPHYSICAL WELL LOGGING AT

# GRAM PANCHAYAT- KADEKA, BLOCK- DATAGANJ, DISTT- BADAUN UNDER JAL JIVAN MISSION

#### Introduction:

A Deep bore hole was drilled 130 mtrs. depth. and Logged depth 130 mtrs. at above site. Was drilled by M/S PNC-SPML-JV, Badaun.

On the request of M/S PNC-SPML-JV, Badaun. a Geophysical well Logging in the above bore hole using IGIS Well Logger on 18.Aug.2023.

Logging Para meters - Self potential, short normal (N-16), Long Normal (N-64), Lateral. Details of major aquifer formations explored from logging of bore hole combined with the study of Strata Chart prepared from drill cuttings are given in the following table:-

S.No.	Depth	Thickness(m)	Lithology	Expected Water
	range(m)			Quality
1.	0 - 5	5	Surface soil	
2.	5 - 8	3	Clay kankar	
3.	8 - 17	9	Fine to Medium sand	
4.	17 - 23	6	Clay kankar	
5.	23 - 35	12	Medium sand	Medium
6.	35 - 40	5	Clay kankar	
7.	40 - 60*	20	Medium sand & kankar	Medium
8.	60 - 65	5	Clay kankar	
9.	65 - 75*	10	Medium sand	Medium
10.	75 - 81	6	Clay kankar	
11.	81 - 91*	10	Medium sand	Medium
12.	91 - 97	6	Clay kankar	
13.	97 - 102*	5	Fine to Medium sand	Medium
14.	102 - 106	4	Clay kankar	
15.	106 - 117*	11	Medium sand	Medium
16.	117 - 120	3	Clay kankar	
17.	120 - 126*	6	Medium sand	Medium
18.	126 - 130	4	Clay kankar	

Ground Water Survey Consultancy

#### Conclusions and Recommendations :-

- 1. The Lithology broadly tallies with that of drill cutting starta chart.
- 2. The zones marked with asterisk (\*) appear to be aquifer zones for possible development of tube well.
- The Quality of water is expected Medium.
- 4. It is recommended to have a chemical and bacteriological analysis of the water sample before using it for human consumption or for any other use.
- 5. All projections and recommendations are subject to the inherent limitations of the technique employed and there could be variations as the underground conditions are not always amenable to physical interpretations.

Agra \* Agra

Geophysicist

**Ground Water Survey Consultancy** 

IGIS/S/02/22-23 GROUND WATER
SURVEY
CONSULTANCY
AGRA, UP, INDIA logging Details

ingreg Strates

through Contact

Contact logger Owned by: DMPL-2 logger Mode Rho a N16 (SN, LAT SE (MIN) m V -10-20ğ õ 0 o. 3-8-23-8-**%**-8-\$-MANA 8-S-1000 8 Depth (m) 65 8-٦-8-8-8g-ਫ਼-ਤ-5 15 8-13 8-17

