(COMPLETE GROUND WATER SERVICE PROVIDER)

Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005

Email: - firstbestsolution@yahoo.com

Mob: - 8744928231 Date:25-5-2024

Geophysical Borehole Logging Report By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Khargupur, Block Rupaideeh, District Gonda, U.P.

Name of Village: Khargupur

Block - Rupaideeh District: Gonda

Date

: 25-5-2024

Depth logged: 164.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular zones have been deciphered.

S.No	Depth Range (m.bgl)		Thickness (m)	LITHOLOGY
	From	То		
1	6	8	2	fine sand
2	8	11	3	Clay with kankar
3	11	44	33	fine sand
4	44	48	4	Clay with kankar
5	48	75	27	fine sand
6	75	79	4	Clay with kankar
7	79	87	8	fine sand
8	87	90	3	Clay with kankar
9	90	92	2	fine sand
10	92	98	6	Clay with kankar
11	98	102	4	fine sand
12	102	104	2	Sandy Clay
13	104 🕳	114	10	fine sand
14	114	118	4	Sandy Clay
15	118 🗸	129	11	fine sand
16	129	138	9	Sandy Clay
17	138 🕶	146	8	fine sand
18	146	148	2	Sandy Clay
19	148	155	7	fine sand



