
Malawa



2. Quality of ground water is deteriorating marginal to saline in between 83 m mgl to till depth logged

Total Lowering	=	79.970m
B.G.L	=	79.470m
A.G.L	=	0.500m
4. 300 X 200 mm@ Reducer	=	0.000m
3. 300 mm@ Slotted Pipe	=	18.330m
2. 200 mm@ Plain Pipe	=	0.000m
1. 300 mm@ Housing Pipe	=	61.640m

Junior Engineer