

Aqua Xplore

(Groundwater Assessment & Allied Services) 243/5, New Colony Jiyamau, Hazratganj, Lucknow – 226001 Mob. 9918202546 / 9889323322, Email-aquaxplorelko@gmail.com

Advisor- Dr. R. A. Yadav, ex- Manager (Groundwater), U. P. Jal Nigam

Ref 1015 - S / AX - 2023 Date 15.10.2023

## **Geophysical Borehole Logging Report**

Name of the site : Sultanpur, Block - Ranipur

District : Mau Date : 15.10.2023 Depth logged : 165.0 mbgl Depth drilled : 165.0 mbgl- as reported

Logger used : Robertson make

Presence : Representative of M/S KLSR and RAYS (JV)., Mau

Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water;

SI.No.	Depth range(mbgl)	Thickness(m)	Remarks
1	32.0—36.0	4.0	
2	53.0-57.0	4.0	Good all
3	85.0—92.0	7.0	
4	97.0—110.0	13.0	
5	116.0—120.0	4.0	

Note. All zones are intermixed with kankar.No suitable zone were encountered below 120.0 mbgl till depth logged.

Ę.

for Aqua Xplore

CC;

R.

1. M/S KLSR and RAYS (JV)., Mau, Uttar Pradesh

 $\mathcal{T}_{i_1}$