



Aqua Xplore

(Groundwater Assessment & Allied Services)

243/5, New Colony Jiyamau, Hazratganj, Lucknow – 226001

Mob. 9918202546 / 9889323322, Email-aquaxploreelko@gmail.com

Advisor- Dr. R. A. Yadav, ex- Manager (Groundwater), U. P. Jal Nigam

Ref 916 - A / AX - 2023

Date 20.08.2023

Geophysical Borehole Logging Report

Name of the site : Sigadi, Block – Ranipur

District : Mau

Date : 20.08.2023

Depth logged : 170.0 mbgl

Depth drilled : 170.0 mbgl- as reported

Logger used : Robertson make

Presence : Representative of M/S KLSR and RAYS (JV)., Mau

Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water;

Sl.No.	Depth range(mbgl)	Thickness(m)	Remarks
1	20.0—26.0	6.0	Good all
2	35.0—42.0	7.0	
3	55.0—65.0	10.0	
4	70.0—83.0	13.0	

Note. All zones are intermixed with kankar. Quality of the formation water is Deteriorating marginal to saline below 85.0 mbgl till depth logged

for Aqua Xplore

CC;

1. M/S KLSR and RAYS (JV)., Mau, Uttar Pradesh