RST BEST SOLUTIONS

(COMPLETE GROUND WATER SERVICE PROVIDER) Plot No. V21, Flat No. 10, Vikram Enclave Shalimar Garden, Sahibabad, Ghaziabad-201005 Email: -firstbestsolution@vahoo.com Mob: - 8744928231

Date:19-12-2023

GeophysicalBoreholeLoggingReport By Sh. R. Chandra, Sr. Scientist (Retd.)

The geo-electric logging was done in the borehole at village Panwapur,

BlockUtraula, District Balrampur, U.P.

Name of Village :Panwapur(82°24'16" E,27°'18'54"N)

Block – Utraula

District: Balrampur

Date

: 19-12-2023

Depth logged: 164.0 mbgl

Logger use

: Robertson

Based on the Interpretation report from geophysical Log chart following granular

zones have been deciphered.

en deciphered.			
Depth Range S.No (m.bgl)		Thickness (m)	LITHOLOGY
From	To		1
6	25	19	fine sand
25	30	5	Clay with kankar
	39	9	fine sand
	45	6	Clay with kankar
	80	- 35	fine sand
	84	. 4	Clay with kankar
	98	14	fine sand
	106	8	Clay with kankar
	115	9	fine sand
115	120	5	Clay with kankar
120	139	19	fine sand
139	150	. 11	Clay with kankar
	160	10	fine sand
		4	sandy clay
	Pepth Ri (m.bg From 6 25 30 39 45 80 84 98 106 115 120	Depth Range (m.bgl) From To 6 25 25 30 30 39 39 45 45 80 80 84 84 98 98 106 106 115 115 120 120 139 139 150 150 160	Depth Range (m.bgl) Thickness (m) From To 5 6 25 19 25 30 5 30 39 9 39 45 6 45 80 35 80 84 4 84 98 14 98 106 8 106 115 9 115 120 5 120 139 19 139 150 11 150 160 10

For First Best Solution

Authorized Signatory

For First Best Solution

Proprietor