

SURYA BOREWELL & TRADERS

Address – Sikandra, Kanpur Dehat

Ref No: - 29-01-39/ SURYA/2024

Date: 29 Jan 2024

GEOPHYSICAL WELL LOGGING REPORT

Site Location

: Vill - Beninagar Block - Gainsari

District

: Balrampur

Drilled Depth

: 276 m bgl

Borehole drilled by

: Dara Eco Protection (JV) Balrampur.

Logged Depth

:276 m bgl

Date of Logging

: 28 Jan 2024, 16:50 hrs

Rm & Rsw

: 14.20 Ω-m & 15.20 Ω-m

Lat. & Long.

: 27.424723 & 82.543233.

Based on interpretation of presented geophysical logs (S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones is as mentioned below –

| S.No | Depth Range (in meter below ground level) | | Thickness | Remark (Quality of formation water) |
|------|---|----------|------------|-------------------------------------|
| | From | То | (in meter) | (as appear) |
| 1. | 10 | ₹ 1 37 ≥ | 27 | Good |
| 2. | 41 | 44 | 3 | Good |
| 3. | 59 | 71 | 12 | Good |
| 4. | 80 | 89 | 9 | Good |
| 5. | 102 | 108 | 6 | Good |
| 6. | 117 | 136 | 9 | Good |
| 7. | 132 | 135 | 3 | Good |
| 8. | 141 | 165 | 24 | Good |
| 9. | 176 | 188 | 12 | Good |
| 10. | 193 | 238 | 45 | |
| 11. | 244 | 265 | 21 | Good |
| 12. | 270 | 273 | 3. | Good |

Note: - The interpretation of mentioned geophysical logs reveals that-

- 1. Every granular zone contains fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either highly mixed with clay kanker or very fine.
- 3. Quality of formation water up to logging depth is Good
- 4. Log data Attached.

5.

Geophysical Log Interpreted by

Rejectioner

(Rajeev Kumar)

Geophysicist M. Sc (Tech) Geophysics