GEO-PHYSICAL WELL ELECTROLOGGING REPORT

Ref No- 22-12-31 /SURYA/2023

Date- 27 Dec 2023

DETAILS OF SITE VILLAGE – Sarain Vikram BLOCK – Ramnagar DISTRICT – Jaunpur

ER

 $\Lambda\Lambda$

Borehole Drilled By-Welspun India Ltd

Log Report By-

Surya Borewell & Traders, Sikandra, Kanpur Dehat



Address – Sikandra, Kanpur Dehat

Ref No: - 22-12-31/ SURYA/2023

Date: 27 Dec 2023

GEOPHYSICAL WELL LOGGING REPORT

General Description (As reported)

Site Location	Sarain Vikram, Block- Ramnagar		
District	: Jaunpur		
Drilled Depth	: 340 m bgl		
Borehole drilled by	: Welspun India Ltd.		
Logged Depth	: 330 m bgl		
Date of Logging	: 26 Dec 2023, 15:24 hrs		
Rm & Rsw	: 15.0 Ω-m & 18.2 Ω-m		
Lat. & Long	:26.2644 & 82.5413		

Based on interpretation of presented geophysical logs (S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones is as mentioned below –

Ser No	Depth F (in meter below From		Thickness (in meter)	Remark (Quality of formation water) (as appear)
1.	7	12	5	Good
2.	29	36	7	Good
3.	94	103	9	Good
4.	116	120	4	Good
5.	160	166	6	Good
6.	173	184	11	Good
7.	198	204	6	Good
8.	218	230 ⁻ E K	12	Good
9.	242	248	6	Good
10.	258	262	4	Good
11.	272	275	3	Good

Note: - The interpretation of mentioned geophysical logs reveals that-

- 1. Every granular zone contains fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either highly mixed with clay kanker or very fine.
- 3. At depth range (37-97) m bgl, (104-115) m bgl & (121-140) m bgl quality of formation water appears to be saline in nature.
- 4. Log data Attached.

Geophysical Log Interpreted by

Rojesikemor

(Rajeev Kumar) Geophysicist M. Sc (Tech) Geophysics

