



Medini

GSTIN : 09BDGPB5432F12V

Shri Medini

E-11, South City, Raebareli Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 31-01(i)/JJM/Logging/2022-23

Dated : 01-02-2023

GEOPHYSICAL WELL LOGGING REPORT

Village : Mahamau
Block : Jagdishpur
District : Amethi
Date of Logging : Jan. 31, 2023
Logged Depth : 163 mbgl.
Borehole Drilled By : HETVI CONSTRUCTION LLP
Drilled Depth : 168 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6") following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	17	22	05	Good
2	27	46	19	Good
3	56	62	06	Good
4	82	90	08	Good
5	93	102	07	Good

Note :-

Above mentioned E.Logs/parameters reveals:-

- Above mentioned groups contains fine sediments.
- That zone at s.nos. 2 mixed with kanker.
- Borehole contains granular zones other than mentioned above are either very finer sediments or dominated with clay.
- Below 108 mts. till logged depth i.e. 163 mbgl. borehole contain deteriorated/saline quality of formation water.

For Shri Medini

(Signature)
(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.

*Verified as per
logs provided
Note - S.Nos - 98-102
(4m)*



G.Su
01/02/23