



Medini

GSTIN : 09BDGPB5432112V

Shri Medini

E-11, South City, Raebarell Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 05(i)-12/JJM/Logging/2022-23

Dated : 05-12-2022

GEOPHYSICAL WELL LOGGING REPORT

Village : Mirzagarh
Block : Singpur
District : Amethi
Date of Logging : Dec. 05, 2022
Logged Depth : 166 mbgl.
Borehole Drilled By : HETVI CONSTRUCTION LLP
Drilled Depth : 170 meters (as reported)


Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	21	25	04	Good
2	30	32	02	Good
3	35	39	04	Good
4	47	54	07	Good
5	57	60	03	Good
6	70	75	05	Good

Note :-

- Above mentioned groups contains fine sediments.
- Below 90 meters borehole contains marginal quality and below 104 meters Deteriorated/ Saline quality of formation water .
- Borehole contains granular zones other than mentioned above are finer sediments or dominated with clay.

For Shri Medini



(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.



Verified as per
logs provided

G.Sh
06/12/22