



# Medini

GSTIN : 09BDGPB5432F12V

*Shri Medini*

E-11, South City, Raebareli Road,  
Lucknow-226025

E-mail.: shril.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 12-02(i)/JJM/Logging/2022-23

Dated : 11-02-2023

## GEOPHYSICAL WELL LOGGING REPORT

Village : Paliya Chandpur  
Block : Musafirkhana  
District : Amethi  
Date of Logging : Feb. 12, 2023  
Logged Depth : 149 mbgl.  
Borehole Drilled By : **HETVI CONSTRUCTION LLP**  
Drilled Depth : 165 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	15	24	09	Good
2	30	46	16	Good
3	86	89	03	Good

**Note :-**

Above mentioned E.Logs/parameters reveals:-

- Above mentioned groups contains fine sediments.
- Zone at S.Nos. 4 & 5 mixed with Kanker.
- Borehole contains granular zones other than mentioned above are either very finer sediments or dominated with clay.
- Below 104 mts. till logged depth borehole contain deteriorated/saline quality of formation water.

For Shri Medini

*R.K. BAJPAI*

(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,

Retired from Irrigation Department (Mechanical),

Uttar Pradesh, LUCKNOW.

*Verified as per  
logs provided*

*GSh  
13/02/23*

