



Medini

GSTIN : 09BDGPB5412112V

Shri Medini

E-11, South City, Raebareli Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 09-12(ii)/JJM/Logging/2022-23

Dated : 09-12-2022

GEOPHYSICAL WELL LOGGING REPORT

Village : Pindara Parera
Block : Singpur
District : Amethi
Date of Logging : Dec. 09, 2022
Logged Depth : 170 mbgl.
Borehole Drilled By : HETVI CONSTRUCTION LLP
Drilled Depth : 167 meters (as reported)


Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	27	32	05	Good
2	36	45	09	Good
3	38	45	06	Good
4	67	77	10	Good
5	101	114	13	Moderate
6	143	146	03	Moderate
7	148	154	06	Moderate

Note :-

- Above mentioned groups contains fine sediments.
- Borehole contains granular zones other than mentioned above are finer sediments or dominated with clay/kanker.
- Below 163 mts. to logged depth i.e. 167 mbgl. borehole contain deteriorated/brakish quality of formation water.

For Shri Medini


(R.K. BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.



Verified as per
logs provided
GSh
12/12/22