



Medini

24 20

GSTIN : 09BDGPB5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No.: 23-12(i)/JJM/Logging/2022-23

Dated : 20-06-2022

GEOPHYSICAL WELL LOGGING REPORT

Village : Rajapur
Block : Singpur
District : Amethi
Date of Logging : Dec. 23, 2022
Logged Depth : 162 mbgl.
Borehole Drilled By : HETVI CONSTRUCTION LLP
Drilled Depth : 165 mts. (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered -

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	20	24	04	Good
2	30	35	05	Good
3	49	59	10	Good
4	66	71	05	Good

Note :-

- Above mentioned group contains fine sediments.
- Borehole contains granular zones other than mentioned above are very thin and highly dominated with clay and very finer sediments.
- Below 79 mts. to till logged depth i.e. 162 mbgl, borehole contain Deteriorated/Saline quality of formation water.

For Shri Medini

R.K. BAJPAI

(R.K. BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.

Verified as per
logs provided



G.Sh
24/12/22