



Medini

GSTIN : 09BDGPB5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 24-12(ii)/JJM/Logging/2022-23

Dated : 25-06-2022

GEOPHYSICAL WELL LOGGING REPORT

Village : Sadiya
Block : Singpur
District : Amethi
Date of Logging : Dec. 24, 2022
Logged Depth : 165 mbgl.
Borehole Drilled By : HETVI CONSTRUCTION LLP
Drilled Depth : 165 mts. (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered -

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	21	26	05	Good
2	31	62	31	Good
3	64	71	07	Good
4	81	84	03	Good
5	102	113	11	Good

Note :-

E.Logs reveals that:-

- Borehole contains granular zones other than mentioned above are very thin and highly dominated with clay and very finer sediments.
- Below 117 mts. to till logged depth i.e. 165 mbgl. borehole contain Deteriorated/Saline quality of formation water.

For Shri Medini

R.K. BAJPAI

(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,

Retired from Irrigation Department (Mechanical),

Uttar Pradesh, LUCKNOW.



*Verified as per
logs provided
S.No 2 is*

*Note -
Highly intermixed
with kankar*

*GSh
26/12/22*