



# Medini

GSTIN: 09BDGPB5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,  
Lucknow-226025

E-mail: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 05(ii)-12/JJM/Logging/2022-23

Dated : 05-12-2022

## GEOPHYSICAL WELL LOGGING REPORT

Village : Satan Purwa  
Block : Singpur  
District : Amethi  
Date of Logging : Dec. 05, 2022  
Logged Depth : 159 mbgl.  
Borehole Drilled By : HETVI CONSTRUCTION LLP  
Drilled Depth : 170 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	22	28	06	Good
2	54	86	32	Good
3	95	100	05	Good
4	138	145	07	Good

### Note :

- Above mentioned groups contains fine sediments.
- Borehole contains granular zones other than mentioned above are finer sediments or dominated with clay.

For Shri Medini

  
(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,  
Retired from Irrigation Department (Mechanical),  
Uttar Pradesh, LUCKNOW.



Verified as per  
logs provided  
Note: Sr No 2  
54-58 (4m)  
65-75 (10m)  
80-86 (6m)

G. Sh  
06/12/22