



Medini

GSTIN : 09BDGPR5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,
Lucknow-226025

E-mail.: shri.medini@gmail.com

Mob.: 9554412795, 8887691798

Ref. No. : 16-12(ii)/JJM/Logging/2022-23

Dated : 16-12-2022

GEOPHYSICAL WELL LOGGING REPORT

Village : Satan Purwa
Block : Singpur
District : Amethi
Date of Logging : Dec. 16, 2022
Logged Depth : 106 mbgl.
Borehole Drilled By : HETVI CONSTRUCTION LLP
Drilled Depth : 170 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6") following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
1	20	25	05	Good
2	34	37	03	Good
3	48	55	07	Good
4	67	71	04	Good
5	74	84	10	Good

Note :-

- Zone at S.No. 4 contains finer sediments
- Borehole contains granular zones other than mentioned above are finer sediments or dominated with clay and kanker.

For Shri Medini

R.K. BAJPAI
(R.K. BAJPAI)

Hydrologist & Ground Water Consultant,
Retired from Irrigation Department (Mechanical),
Uttar Pradesh, LUCKNOW.

*Verified as per
logs provided*



gsh