GEO-PHYSICAL WELL ELECTROLOGGING REPORT RefNo-06-07-01/SURYA/2024 Date-06 Jul2024 **DETAILS OF SITE LOCATION - Tikri BLOCK - Puredalai** DISTRICT - Barabnki ER TOGETHER

Borehole Drilled By-

Mega Engineering & Infrastructure ltd.

Log Report By-

Surya Borewell & Traders, Sikandra, Kanpur Dehat

GST No. - 09BKAPM7283A3Z6

Mob - 09451000641

SURYA BOREWELL & TRADERS

Siknda Kanpur Dehat

RefNo:-06-07-01/SURYA/2024

Date:06July2024

GEOPHYSICAL WELL LOGGING REPORT

Site Location	: Tikri				
Block	: Puredalai				
District	: Barabanki				
Drilling Company	: Mega Engineering & Infrastructure ltd.				
Drilled Depth	: 164 m bgl				
Logged Depth	: 164 m bgl				
Date of Logging	06 July 2024,10:28hrs				
Rm & Rsw	3.4 Ω-m & 14.8 Ω-m				
Lat & Long	: 26.876017 & 81.765194				

ŝ

Based on interpretation of presented geophysical logs (S.P., Short Normal N16", Long Normal N64" and Lateral 6'), the location of comparatively suitable granular zones is as mentioned below –

S.No	Depth Range (in meter below ground level)		Thickness	Remark (Quality of formation water)
	From	To	(in meter)	(as appear)
1.	10	80	20	Good
2.	31	50	19	Good
3.	60	71	11	Good
4.	85	120	35	Good
5.	125	142	17	Good
6.	150	164	14	Good

Note: - The interpretation of mentioned geophysical logs reveals that-

- 1. Every granular zone contains fine sediments with kanker as per the data given in the table.
- 2. Granular zones other than mentioned above are either highly mixed with clay kanker or very fine..

Geophysical Log Interpreted by

Pojankinnor

(Rajeev Kumar) Geo-Physicist/Geo-Scientist M. Sc (Te