



Aqua Xplore

(Groundwater Assessment & Allied Services)

243/5, New Colony Jiyamau, Hazratganj, Lucknow – 226001

Mob. 9918202546 / 9889323322, Email-aquaxploreko@gmail.com

Advisor- Dr. R. A. Yadav, ex- Manager (Groundwater), U. P. Jal Nigam

Ref 131 - C / AX - 2025 31.01.2025

Geophysical Borehole Logging Report

Name of the site : Chhichhor Karaundi, Block – Ratanpura

District : Mau

Date : 31.01.2025

Depth logged : 190.0 mbgl

Depth drilled : 200.0 mbgl- as reported Rmf-10.5 Ohm-m Rw-12.5 Ohm-m

Logger used : Robertson make

Presence : Representative of M/S L.C.Infra Projects Pvt. Ltd. Mau

Based on the interpretation of geophysical logs, following information may be deciphered, particularly with respect to salinity of the formation water;

Sl.No.	Depth range(mbgl)	Thickness(m)	Remarks
1	12.0–19.0	7.0	Good all
2	39.0–46.0	7.0	
3	56.0–64.0	8.0	
4	92.0–96.0	4.0	
5	98.0–102.0	4.0	
6	130.0–140.0	10.0	
7	148.0–158.0	10.0	

Note. All zones are intermixed with kankar.

for Aqua Xplore

CC;

1. M/S L.C. Infra Projects Pvt. Ltd., Mau