



# Medini

GSTIN : 09BDGPB5432F12V

*Shri Medini*

E-11, South City, Raebareli Road,  
Lucknow-226025

E-mail.: [shri.medini@gmail.com](mailto:shri.medini@gmail.com)

Mob.: 9554412795, 8887691798

Ref. No. : 22-01/JJM/Logging/2022-23

Dated : 20-01-2023

## GEOPHYSICAL WELL LOGGING REPORT

Village : Tiloi  
Block : Tiloi  
District : Amethi  
Date of Logging : Jan. 22, 2023  
Logged Depth : ~~169~~ mbgl.  
Borehole Drilled By : HETVI CONSTRUCTION LLP  
Drilled Depth : 175 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	To		
<del>1</del>	16	19	03	Good
<del>2</del>	24	29	05	Good
3	32	37	05	Good
4	39	43	04	Good
5	47	50	03	Good
<del>6</del>	54	57	03	Good
<del>7</del>	80	88	08	Good

Note :-

- Above mentioned groups contains fine sediments.
- Borehole contains granular zones other than mentioned above are finer sediments or dominated with clay.
- Below 96 mts. till logged depth i.e. 169 mbgl. borehole contain deteriorated/brakish quality of formation water.

For Shri Medini

*R.K. BAJPAI*  
(R.K. BAJPAI)

Hydrologist & Ground Water Consultant,  
Retired from Irrigation Department (Mechanical),  
Uttar Pradesh, LUCKNOW.

*Verified as per  
logs provided  
Note-Sr No 3 to 5  
have finer  
sediments*



*1  
GCh  
23/01/23*