

GSTIN:: 09BDGPB5432F1ZV

Shri Medini

E-11, South City, Raebareli Road,

Lucknow-226025

E-mail.: shri.medini@gmail.com Mob.: 9554412795, 8887691798

Ref. No.: 31-01(iii)/JJM/Logging/2022-23

Dated: 01-02-2023

## GEOPHYSICAL WELL LOGGING REPORT

Village : Khikarwa

Block : Tiloi

District : Amethi

Date of Logging : Jan. 31, 2023

Logged Depth : 160 mbgl.

Borehole Drilled By: Vindhya Telelinks – Gaja Engineering PVT. Ltd. (J.V.)

Drilled Depth : 170 meters (as reported)

Based on interpretation of geophysical logs (Self Potential S.P., Short Normal N16", Long Normal N64" and Lateral 6') following granular zones have been deciphered –

S. no.	Depth Range (in meter below ground level)		Thickness (in meter)	Remark (Quality of formation water)
	From	То	- 1. No. 200 200 200 200 200 200 200 200 200 20	***
X	16	20	04	Good
2	24	29	05	Good
8	34	41	07	Good
\$	50	54	04	Good
0/	61	67	06	Good
6	78	88	10	Good

Note :-

Above mentioned E.Logs/parameters revels:-

Above mentioned groups contains fine sediments.

Granular zones in between depth range 34 to 67 mts. mixed with kanker.

iii. Borehole contains granular zones other than mentioned above are either very finer sediments or dominated with clay.

Below 96 mts. till logged depth i.e. 166 mbgl. borehole contain deteriorated/saline quality of formation water.

For Shri Medini

(R.K.BAJPAI)

Hydrologist & Ground Water Consultant,

Retired from Irrigation Department (Mechanical)

Uttar Pradesh, LUCKNOW.

E-11 South City Lucknow

General