

And Carthon

c.c.

## Phone:- 0522 - 2220173, 2220272 GRAM :- JAL NIGAM

## UTTAR PRADESH JAL NIGAM <u>GEOPHYSICAL LOGGING REPORT</u> 1. Name of the site:- Chandpur, Block Mandhata Marken - 200×150 mm

- 1. Name of the site :- Chandpur, Block Mandhata
- 2. District:- Pratapgarh
- 3. Dt. Of logging:-. 18.02.2021
- 4. Drilled depth( as verified dt. 19.2.21 by concerned JE):- 150.0mbgl
- 5. Logged depth:- 150.0mbgl
- 6. Logger no .:- AquaXplore, Lucknow
- 7. Concerned JE:- Er. Vipin Kumar, JE
- 8. Based on the geophysical log interpretation following granular zones may be deciphered, particularly with respect to salinity of the formation water.

Sl. No.	Zones (mbgl)	Thickness(mts.)	Remarks
1	17.0-32.0	15.0	Good, very fine sand kanker intermixed
2	62.0-66.0	4.0 3	Good, fine sand
3	82.0-98.0	16.0 15	Good, fine sand

Quality of formation water is deteriorating from marginal to saline below 102.0 mbgl till depth logged.

Station

(Dr. S.Sahai) Manager(Groundwater)

1. EE, IInd CD(E/M), UP Jal Nigam, Prayagraj for information and necessary action.

fahar

Manager(Groundwater)